

Appendix 8A. Selected high-water marks for Rock River at Janesville, Wisconsin.

[Location of high-water marks are shown in appendix 8B. Elevation is referenced to North American Vertical Datum of 1988 (NAVD 88). High-water-mark rating: The quality of the high-water marks was subjectively rated in the field as excellent, good, fair, or poor by the high-water-mark crews. Ratings were based on the clarity of the mark and visual or hand-level comparison to nearby marks]

High-water-mark ID	Elevation, in feet	Latitude	Longitude	High-water-mark rating	Description	High-water-mark type
¹ 119	774.4	42.686	-89.026	None recorded	North side of Centerway, east of Main Street	Trash line/stain
¹ 120	775.0	42.690	-89.029	None recorded	East of Main Street north of Hyatt Street at Traxler Park entrance	Trash line/stain
¹ 121	775.8	42.697	-89.032	None recorded	Centerline of boat launch at north Traxler Park	Trash line/stain
¹ 122	775.8	42.706	-89.037	None recorded	South end of Riverside Park, south of shelter	Trash line/stain
¹ 123	775.8	42.703	-89.035	None recorded	Centerline of Elgin Avenue	Trash line/stain
¹ 124	766.5	42.674	-89.017	None recorded	Riverfront Park on River Street, centerline of canoe launch	Trash line/stain
¹ 126	761.1	42.672	-89.035	None recorded	Centerline of Pearl Street at VanGalder bus garage	Trash line/stain
¹ 128	766.3	42.669	-89.013	None recorded	Parking lot of Dawson Field	Trash line/stain
1	757.3	42.633	-89.062	Excellent	Across River Road from river, on power pole	Mud line
2	757.2	42.637	-89.062	Excellent	Between South River Rd and Rock River, on power pole	Mud line
3	757.2	42.641	-89.064	Good	Sapling due north of bridge support	Mud line
4	759.8	42.656	-89.061	Excellent	Bike path overlook with benches, in bark of willow tree	Mud/Debris line
5	760.6	42.668	-89.046	Excellent	Back of park information sign at Rock River Parkway trailhead	None recorded
6	760.0	42.662	-89.056	Excellent	Rusted steel post at southeast corner of bridge on bike path	Mud line
8	757.7	42.644	-89.062	Excellent	Tree across road from 2439 South River Road	Mud/Debris line
9	758.7	42.652	-89.062	Excellent	Maple tree, 1/2 mile north of HWM 3	Mud line
12	762.7	42.670	-89.032	Excellent	Maple tree, between State Highway 51 and railroad bridge	Mud/Debris line
14	765.3	42.669	-89.020	Excellent	Stump on west side of Jeffris Park	Mud line
16	765.2	42.668	-89.027	Good	Behind fence in backyard, bark of sapling	Mud line
17	767.2	42.679	-89.020	Excellent	Birch tree in library parking lot	Mud line
18	767.7	42.681	-89.022	Good	Locust tree at Water Street at end of Lawrence Street	Mud line
19	767.3	42.680	-89.021	Excellent	End of parking lot by river/Water Street at Van Buren, power pole	Mud line
20	769.4	42.683	-89.024	Excellent	Near small waterfront park, fire escape support	Mud line
21	769.6	42.683	-89.023	Excellent	Behind Legends Bar, green electrical box	Mud line
22	769.2	42.683	-89.024	Fair	Mud line on sidewalk	Mud line
23	769.9	42.684	-89.026	Good	Canoe launch ramp, wall and hand rail	Mud/Debris line
24	774.9	42.685	-89.027	Excellent	Between Centerway Avenue and hydroplant	Mud line
25	773.1	42.685	-89.025	Excellent	Across from canoe ramp/ds from dam, red pagoda with benches	Mud line
26	771.6	42.684	-89.024	Excellent	Main Street between Pease Court and Wall Street, tree next to lamp post	Mud line
27	775.3	42.696	-89.033	Good	Kiwanis trailhead, maple tree bark	Kill line of lichens
30	775.3	42.691	-89.033	Excellent	Close to HWM 29, large cottonwood tree	Water line

¹Surveyed by City of Janesville, June 24, 2008.