

Appendix 5A. Selected high-water marks for Crawfish River at Milford, Wisconsin.

[Location of high-water marks are shown in appendix 5B. Elevation is referenced to North American Vertical Datum of 1988 (NAVD 88). High-water-mark rating: The quality of the high-water marks was subjectively rated in the field as excellent, good, fair, or poor by the high-water-mark crews. Ratings were based on the clarity of the mark and visual or hand-level comparison to nearby marks]

High-water-mark ID	Elevation, in feet	Latitude	Longitude	High-water-mark rating	Description	High-water-mark type
6	792.8	43.101	-88.850	Not recorded	Debris in tree branches	Debris line
9	792.3	43.102	-88.850	Good	Grass in tree bark	Debris line
17	792.7	43.099	-88.848	Excellent	Owner indicated line on shed	Landowner
19	792.2	43.099	-88.849	Excellent	On tree trunk	Stain line
21	792.1	43.095	-88.846	Fair	Bug casing at the water line, downstream right bank bridge	Debris line
24	792.1	43.100	-88.847	Good	Line on tree	Seed/mud line
23	791.8	43.100	-88.849	Fair	Deck post	Debris line
10	795.4	43.104	-88.854	Good	Grass in tree	Debris line