

Appendix 3A. Selected high-water marks table for Kickapoo River at La Farge, Wisconsin.

[Location of high-water marks are shown in appendix 3B. Elevation is referenced to North American Vertical Datum of 1988 (NAVD 88). High-water-mark rating: The quality of the high-water marks was subjectively rated in the field as excellent, good, fair, or poor by the high-water-mark crews. Ratings were based on the clarity of the mark and visual or hand-level comparison to nearby marks]

High-water-mark ID	Elevation, in feet	Latitude	Longitude	High-water-mark rating	Description	High-water-mark type
5	795.7	43.567	-90.641	Poor	Large maple tree	Debris line tree
6	795.0	43.566	-90.640	Poor	Large tree	Seed/debris line
8	797.3	43.574	-90.643	Poor	Large maple tree	Seed/debris line
11	796.3	43.570	-90.642	Fair	None recorded	Seed/debris line
13	795.0	43.565	-90.639	Not recorded	None recorded	Debris line
14	796.3	43.572	-90.639	Excellent	Water mark on Public Works building	Stain line
15	797.9	43.576	-90.645	Fair	None recorded	Seed/debris line
16	799.0	43.579	-90.645	Fair	None recorded	Debris line
19	800.7	43.585	-90.643	Not recorded	None recorded	Seed/debris line
25	793.9	43.569	-90.642	Not recorded	New HWM on tree	Grass line
26	797.6	43.575	-90.645	Good	In trunk of 12-foot boxelder tree	Debris line
27	800.4	43.584	-90.643	Not recorded	Near bridge, upstream, left bank, small boxelder branches	None recorded
28	802.1	43.587	-90.641	Not recorded	None recorded	None recorded
29	801.2	43.588	-90.645	Good	Boxelder tree	Mud line
31	797.9	43.575	-90.642	Excellent	Lumberyard building	Mud line