

Appendix 4A. Selected high-water marks for Kickapoo River at Gays Mills, Wisconsin.

[Location of high-water marks are shown in appendix 4B. Elevation is referenced to North American Vertical Datum of 1988 (NAVD 88). High-water-mark rating: The quality of the high-water marks was subjectively rated in the field as excellent, good, fair, or poor by the high-water-mark crews. Ratings were based on the clarity of the mark and visual or hand-level comparison to nearby marks]

High-water-mark ID	Elevation, in feet	Latitude	Longitude	High-water-mark rating	Description	High-water-mark type
1	705.0	43.318	-90.846	Not applicable	Bench mark - USACE (fire hydrant)	NA
2	704.9	43.317	-90.845	Good	Book return box at library	Stain line
3	704.1	43.317	-90.845	Excellent	Marker on concrete walk	Seed line, landowner
4	704.1	43.317	-90.847	Excellent	Seeds in window screen	Seed line
5	704.3	43.317	-90.848	Excellent	Brown stain on abandoned house	Stain line
8	704.8	43.318	-90.848	Excellent	Vet marked spot on front walk	Landowner
9	704.5	43.318	-90.847	Excellent	Barbershop pole	Stain line
10	704.2	43.316	-90.847	Excellent	Stainline on mailbox	Stain line
11	704.3	43.315	-90.846	Good	Faded water line on church sign	Stain line
12	704.0	43.315	-90.847	Fair	Line on white door, flammable storage	Stain line
15	701.7	43.307	-90.857	Poor	Weak, multiple lines, on power pole	Mud line
16	702.1	43.307	-90.857	Fair	Mud/tree discoloration	Mud line
17	703.4	43.312	-90.853	Good	In horse pasture, mud on leaves, very clear	Mud line
19	703.9	43.316	-90.853	Fair/poor	Faint mud line	Mud line
20	705.0	43.319	-90.847	Excellent	North side of garage	Stain line
21	705.0	43.319	-90.845	Excellent	Brown line on garage	Water line
22	705.5	43.319	-90.844	Excellent	Gray line on garage at north end of Rebecca Street	Water line
23	705.2	43.317	-90.842	Excellent	Brown line on side of white garage	Water line
24	704.4	43.315	-90.845	Excellent	Side of house near Highway 131	Water line
25	703.8	43.314	-90.848	Good	Sign at end of Railroad Street near public pool	Water line
26	702.5	43.311	-90.849	Good	Trees in logging area	Mud line
101	705.8	43.322	-90.840	Good	Faint color line on maple tree	Water line
102	705.6	43.324	-90.841	Fair	Bark discoloration on elm tree	Mud line
103	706.9	43.327	-90.840	Poor	Line on leaves	Mud line
104	708.5	43.336	-90.849	Good	Ash tree near old building	Mud line
105	709.7	43.345	-90.849	Good	Tree, near blue bus on floodplain	Mud line
106	710.6	43.353	-90.846	Good	Walnut tree, on edge of field	Mud line