

Appendix 6A. Selected high-water marks for Rock River at Jefferson, Wisconsin.

[Location of high-water marks are shown in appendix 6B. Elevation is referenced to North American Vertical Datum of 1988 (NAVD 88). High-water-mark rating: The quality of the high-water marks was subjectively rated in the field as excellent, good, fair, or poor by the high-water-mark crews. Ratings were based on the clarity of the mark and visual or hand-level comparison to nearby marks]

High-water-mark ID	Elevation, in feet	Latitude	Longitude	High-water-mark rating	Description	High-water-mark type
¹ J7	788.6	43.000	-88.808	Not applicable	County survey, none recorded	None recorded
¹ J8	788.9	43.002	-88.812	Not applicable	County survey, none recorded	None recorded
¹ J14	789.0	43.003	-88.809	Not applicable	County survey, Jefferson Dam	None recorded
8	788.3	42.998	-88.806	None recorded	Mud line on fence; clear	Mud line
25	789.6	43.013	-88.812	Excellent	Blue line on twin trunk stump	Seed line
29	789.9	43.028	-88.814	Fair	On honeysuckle	Stain line
30	789.8	43.030	-88.813	Good	In willow tree bark, left bank	Seed line
32	789.9	43.034	-88.811	Fair	On boxelder tree, left bank	Stain line
34	790.3	43.036	-88.810	Good	On tree bark	None recorded
36	789.8	43.031	-88.815	Good	In walnut tree bark	Debris line
39	789.7	43.024	-88.817	None recorded	On elm tree bark	Mud line
40	789.6	43.023	-88.817	None recorded	On lamp pole	Mud line
41	789.7	43.021	-88.817	Excellent	Mark on steps, matches boat dock cover	Landowner
45	789.6	43.014	-88.815	None recorded	Mark on black pole	Landowner
49	789.6	43.009	-88.812	Good	On shed, upstream from walking bridge	Mud line
57	788.6	42.996	-88.807	Good	Tree 20 feet downstream of gaging station	Mud line
58	788.5	42.995	-88.805	Good	downstream 1,000 feet from bridge, silver maple	Seed/mud line
62	788.6	42.993	-88.802	None recorded	On tree bark	Mud line
61	788.5	42.993	-88.800	None recorded	On tree bark	Mud line

¹Surveyed by Jefferson County, June 18, 2008.